# **Rotary Damper**


Bi-Directional Uni-Directional

### FRT/FRN-C2 Series

**RoHS Compliant** 

Products specification might be changed without notice.





## **Specifications**

Model	Rated torque	Damping direction
FRT-C2-201 (G1)	(20±6)×10 <sup>-3</sup> N∙m 200±60 gf∙cm	Both directions
FRT-C2-301 (G1)	(30±8)×10 <sup>-3</sup> N∙m 300±80 gf∙cm	Both directions
FRN-C2-R301 (G1)	(30±8)×10 <sup>-3</sup> N∙m 300±80 gf∙cm	Clockwise
FRN-C2-L301 (G1)		Counter <b>-</b> clockwise

Note 1) Rated torque measured at a rotation speed of 20rpm at 23°C Note 2) Gear model number has G1 at the end

- Note 3) Torque can be customized by changing the oil viscosity (see Customizable Torque Chart on page 178)
- There are dampers that generate torque in both directions and one-way torque in the CW direction or CCW direction when the rotating axle is viewed from the top.

- \* Max. rotation speed 50rpm \* Max. cycle rate 10cycle/min
- \* Operating temperature 0 ~50℃
- FRT-C2: 2.1g (with gear: 2.4g) \* Weight FRN-C2:3.2g(with gear:3.5g)
- \* Body and cap material Polycarbonate (PC)
- Polyacetal (POM) \* Rotating shaft material
  - metal (FRT: POM, FRN: SUS)
- \* Gear material Polyacetal (POM)
- \* Oil type Silicone oil

# **Gear Specifications**

Туре	Profile shifted spur gear
Tooth profile	<b>I</b> nvolute
Module	0.8
Pressure angle	20°
Number of teeth	11
Pitch circle diameter	φ8.8

### **Damper Characteristics**

### 1. Speed characteristics

A rotary damper's torque varies according to the rotation speed. In general, as shown in the graph to the right, the torque increases as the rotation speed increases, and the torque decreases as the rotation speed decreases. In addition, please note that the starting torque slightly differs from the rated torque.

#### 2. Temperature characteristics

A rotary damper's torque varies according to the ambient temperature. In addition, as shown in the graph to the right, the torque decreases as the ambient temperature increases, and the torque increases as the ambient temperature decreases. This is because the viscosity of the silicone oil inside the damper varies according to the temperature. When the temperature returns to normal, the torque will return to normal as well.

